

South Coast Air Quality Management District Facility Equipment List Report

Facility: 499 ARND
 Last inspection: 07/17/2012
 SIC: 2822
 Inspector: HLO2 MAY LO
 Inspection Date: 10/01/2010
 Location: Address: 5141 FIRESTONE PL, SOUTH GATE 90280-3650 Sector: LC
 Mailing Address: 5141 FIRESTONE PL, SOUTH GATE 90280-3650 Sector: LC
 Instructions:

MR: 0407
 FS: YS-11 Industrial Sector-based Ins
 Facility Status: Active
 Assignment No.: 1197785
 Disposition: Operating in Compliance at time of inspection

Contact: JOE NEGREY (323) 2497500 x611
 Quarter: 0010 - inspect in 3rd quarter, every year
 On Hold: N
 Facility Team: K
 Suspended: N

RECLAIM N	Permit No.	TITLE V: N	Permit Issue Date	Permit Status	SIP: Equipment Category	AIR: BCAT/CCAT Description	Application Date	Application Status
161368	D01882	08/23/1888	ACTIVE	900266	BCAT	OVEN, PLASTIC/RESIN CURING	10/02/1987	PERMIT TO OPERATE GRANTED
305688	D83235	06/13/1886	ACTIVE	245100	BCAT	FOAMS PLACTIC & RUBBER BLENDING	08/08/1985	PERMIT TO OPERATE GRANTED
320548	F7257	05/20/1997	ACTIVE	245100	BCAT	POLYURETHANE BLENDING	03/21/1997	PERMIT TO OPERATE GRANTED
320547	F7258	05/20/1997	ACTIVE	245100	BCAT	POLYURETHANE BLENDING	03/21/1997	PERMIT TO OPERATE GRANTED
343342	F16142	09/23/1998	ACTIVE	285100	BCAT	POLYURETHANE BLENDING	07/28/1998	PERMIT TO OPERATE GRANTED
407021				900266	BCAT	OVEN, PLASTIC/RESIN CURING	10/18/2002	APPLICATION CANCELLED, KEEP FILING F
413138	F80506	05/13/2003	ACTIVE	74	CCAT	BAGHOUSE, AMBIENT TEMP (<=100 SQ FT)	03/18/2003	PERMIT TO OPERATE GRANTED
437850	F83245	07/19/2006	ACTIVE	299100	BCAT	MISC MATERIALS BLENDING	12/07/2004	PERMIT TO OPERATE GRANTED
437851	F83246	07/19/2006	ACTIVE	299100	BCAT	MISC MATERIALS BLENDING	12/07/2004	PERMIT TO OPERATE GRANTED
C26457	M16966	07/14/1981	ACTIVE	285701	BCAT	POLYURETHANE, REACTION ORGAN ADD	01/01/1990	PERMIT TO OPERATE GRANTED
C26459	M16990	07/14/1981	ACTIVE	285701	BCAT	POLYURETHANE, REACTION ORGAN ADD	01/01/1990	PERMIT TO OPERATE GRANTED
C26458	M16961	07/14/1981	ACTIVE	285701	BCAT	POLYURETHANE, REACTION ORGAN ADD	01/01/1990	PERMIT TO OPERATE GRANTED
C26460	M16962	07/14/1981	ACTIVE	285100	BCAT	POLYURETHANE BLENDING	01/01/1990	PERMIT TO OPERATE GRANTED
C26461	M16963	07/14/1981	ACTIVE	285100	BCAT	POLYURETHANE BLENDING	01/01/1990	PERMIT TO OPERATE GRANTED
C26462	M16994	07/14/1981	ACTIVE	285701	BCAT	POLYURETHANE, REACTION ORGAN ADD	01/01/1990	PERMIT TO OPERATE GRANTED
C26463	M16995	07/14/1981	ACTIVE	285701	BCAT	POLYURETHANE, REACTION ORGAN ADD	01/01/1990	PERMIT TO OPERATE GRANTED
C26464	M16966	07/14/1981	ACTIVE	285100	BCAT	POLYURETHANE BLENDING	01/01/1990	PERMIT TO OPERATE GRANTED
C26465	M16967	07/14/1981	ACTIVE	285100	BCAT	POLYURETHANE BLENDING	01/01/1990	PERMIT TO OPERATE GRANTED
C26466	M16968	07/14/1981	ACTIVE	285701	BCAT	POLYURETHANE, REACTION ORGAN ADD	01/01/1990	PERMIT TO OPERATE GRANTED
C31581	M29785	02/04/1982	INACTIVE	60	CCAT	SPRAY BOOTH PAINT AND SOLVENT	01/01/1980	PERMIT TO OPERATE GRANTED

Inspector: _____ Date: _____ Reviewed By: _____ Date: _____

South Coast Air Quality Management District

Facility Equipment List Report

Run Date: 05/29/2013 10:39 AM

Facility: 499 ARNCO Last inspection: 07/17/2012 SIC: 2822 Inspector: HLO2 MAY LO Inspection Date: 10/01/2010 Location: Address: 5141 FIRESTONE PL, SOUTH GATE 90280-3650 Sector: LC Mailing Address: 5141 FIRESTONE PL, SOUTH GATE 90280-3650 Sector: LC Instruction:	MR: 0407 YS: YS-11 Industrial Sector-based Ins. Facility Status: Active Assignment No.: 1197765 Disposition: Operating in Compliance at time of inspection	Contact: JOE NEGREY (323) 2497500 x611 Quarter: 0010 - inspect in 3rd quarter, every year On Hold: N Facility Team: X Suspended: N
--	--	--

RECLAIM: N		TITLE V: N		SIP:		AIR:	
Application No.	Permit No.	Permit Issue Date	Permit Status	Equipment Category	BCAT/CCAT Description	Application Date	Application Status

Report: 10/1/2010- Applicable Rules: 203(b)
 I arrived at Arnco, facility #499, to perform a compliance inspection. The facility is located at 5141 Firestone Place, South Gate 90280, in Sector LC. The facility manufactures various run-flat tire systems using polyurethane materials that are used to fill construction vehicle tires. I arrived and met with Mr. Jose Quintanilla, Plant Supervisor, 323.249.7500 x315, who accompanied me during my inspection.

The facility operated 12 different mixing tanks/reaction vessels, all of which were operating under valid AQMD permits. All of the tanks that required heat were heated electrically. During my inspection, Mr. Quintanilla informed me that 4 of other tanks that were not being used much were either disconnected or completely removed from the plant. Those tanks were permits M16966, M16967, M16968, and M16969. The facility also operated 1 oven under permit D01862, which was used strictly for softening of raw materials in order to be able to pump the materials. The oven is currently permitted and permit states the oven was electrically heated. However, during our inspection, I discovered that the oven was indeed fueled by natural gas. It was also concluded that the oven is exempt from permitting per R219(c)(3) and as a result of the exemption, Rule 1147 would not be applicable.

Blending tank #18, permit FB3246, is a tank where powder is added and thus, is associated with a baghouse which operates under permit F00006. The baghouse was properly equipped with a magnetic gauge. None of the other permits had any conditions. There were also 4 storage tanks used to store PolyOils, all of which are exempt from permitting per R219(m)(21). The facility was operating in compliance at the time of my inspection and I departed the facility.

Reviewed by MV who wrote: Rule 1155 compliance????

10/29/2010- Applicable Rules: 1147
 I arrived at Arnco, facility #499, to perform a Rule 1147 targeted inspection. I arrived and met with Mr. Jose Quintanilla, Plant Supervisor, who accompanied me during my inspection. I inquired about the oven being operated under Permit D01862. Mr. Quintanilla provided me with a copy of the permit indicating that the equipment was electrically heated. I concluded that the unit was exempt from R1147. I also verified compliance with Rule 1155 and departed the facility.

Inspector: _____ Date: _____ Reviewed By: _____ Date: _____